


Date Created: May 3, 2004

Date Modified:

ACS 200

Equipment Standard Operating Procedure

Greg Allion and Kimberly Appel



1. Purpose

- 1.1. The ACS 200 is used for automated resist coating and development of 4-inch substrates.

2. Reference Documents

- 2.1. Karl Suss ACS 200 manual

3. Equipment

- 3.1. Tweezers
- 3.2. Vacuum wand

4. Materials

- 4.1. AZ 9260 Photo Resist
- 4.2. HMDS Adhesion Promoter
- 4.3. MF 319 Developer
- 4.4. NANO EBR
- 4.5. Nitrogen
- 4.6. Shipley 1813 Photo Resist
- 4.7. Shipley 1827 Photo Resist

5. Protective Equipment


- 5.1. Eye Protection: safety glasses must be worn at all times.
- 5.2. Hand Protection: vinyl or latex gloves.

6. Engineering and/or Administrative Controls

- 6.1. The ACS 200 is located in the Sub micron Room.
- 6.2. The tool owner is Tim Brock. The check off person is Greg Allion, gallion@eecs.umich.edu.
- 6.3. Only authorized user may operate this piece of equipment.
- 6.4. This tool must be reserved in advance for use. Sign up sheets are located on the SSEL Scheduler.
 - 6.4.1. If you sign up for a time slot and cannot make it, then be considerate and remove your name from the sheet.

7. Procedure


- 7.1. Do not open any doors during processing. This will generate an error.
- 7.2. You must always use the scheduler to reserve an opening on this tool.
- 7.3. Overview
 - 7.3.1. Material Handling Unit (MHU): this unit transfers the substrate to the various modules on the system.
 - 7.3.2. Centering Station: centers the substrate on the robots end effector by contact.
 - 7.3.3. Spin Coater: is comprised of a bell shaped cover placed over the chuck and substrate during the spin cycle. The cover closes creating a solvent saturated atmosphere.



- 7.3.3.1. The photo resist is spread evenly over the entire surface by having all parts rotate synchronously as does the confined air inside the cover thus eliminating turbulence (no vortex).
- 7.3.3.2. A solvent saturated atmosphere helps to eliminate usual spinning defects, i.e. rebounding, splash back, comets and striation.
- 7.3.3.3. The standard chuck can accommodate substrates from 3 inch to 8 inch in diameter or 4 inch to 6-inch squares.
- 7.3.3.4. Photo resist coating takes place on the left hand side of the system.
- 7.3.3.5. Spin coating specifications
 - 7.3.3.5.1. Maximum acceleration: 5000rpm/sec
 - 7.3.3.5.2. Minimum acceleration step: 100 rpm/sec
 - 7.3.3.5.3. Maximum substrate thickness: 3mm
 - 7.3.3.5.4. Maximum speed: 7000rpm
 - 7.3.3.5.5. Minimum step: 10rpm

- 7.3.4. Developer Module: the robot handler places the substrate in the developer process chamber. There the substrate is covered with developer while spinning. Spraying the substrate with DI water completes developing.
 - 7.3.4.1. The chuck spins slowly during development and then accelerates at the end for drying with the help of a nitrogen blow.
 - 7.3.4.2. Developing takes place on the right hand side of the system.
 - 7.3.4.3. Developer specifications
 - 7.3.4.3.1. Maximum chuck speed: 6000rpm
 - 7.3.4.3.2. Developer flow rate: 600ml/min
 - 7.3.4.3.3. DI water flow rate: 1800ml/min
- 7.3.5. Hot/Cold/Vapor Prime
 - 7.3.5.1. All three modules are located on the right hand side of the system.
 - 7.3.5.2. The hot plate is used for baking substrates.
 - 7.3.5.2.1. Temperature range is 50°C to 350°C ±0.5°C
 - 7.3.5.3. The cold plate is used for temperature conditioning of substrates.
 - 7.3.5.3.1. Temperature range is 15°C to 30°C ± 0.5°C.
 - 7.3.5.4. Vapor Prime is used to vacuum bake substrates at 90°C.
 - 7.3.5.4.1. Its primary focus is to remove absorbed moisture from the substrate and deliver a uniform and controlled coating of an adhesion promoter (HMDS) to its surface.
 - 7.3.5.4.1.1. Temperature range is 50°C to 250°C.

7.3.6. Wafer Cassette



- 7.3.6.1. There are two (2) cassettes that can be used on the ACS 200. Both cassettes are labeled for this system.
 - 7.3.6.1.1. Do not use the cassettes for any other operations.
- 7.3.6.2. The back portion of the cassette is called the H-Bar.
- 7.3.6.3. The cassette is numbered one (1) through twenty-five (25). The numbering starts at the H-bar (1) and works its way to the front (25) of the cassette.

7.4. Loading a Photo Resist Syringe

- 7.4.1. Make correct adjustments to dispense parameters for a given photo resist.



- 7.4.1.1. Parameters can be found on the door of the ACS.
 - 7.4.2. When making adjustments to the dispense pressure, you must pull it out, you will hear a click. Turn the pressure off then turn to the parameter you need.
 - 7.4.3. Adjust dispense time by using the buttons **below** the digital display.
 - 7.4.4. Use the small dial to adjust the suck backpressure.
 - 7.4.4.1. If the suck backpressure is set to high there will be bubbles in the photo resist.
 - 7.4.5. Clean the dispense connector on the syringe using IPA. Do not use Acetone, this will dissolve the o-ring.
 - 7.4.5.1. Also place a small amount of vacuum grease on the o-ring after cleaning to ensure the o-ring does not dry out and crack.
 - 7.4.6. Choose the appropriate size needle for the syringe you are using.
 - 7.4.7. After use replace the caps on the syringe.
 - 7.4.8. For a full syringe of 9260 photo resists at a thickness of 12 to 13um you should get five (5) wafers coated.
- 7.5. Loading Wafers
- 7.5.1. Know the slot number for the wafer position.
 - 7.5.2. Wafers are loaded with the backside facing the H-bar.
 - 7.5.3. The H-bar on the cassette is placed on the groove. And then push the lock button. The cassette stage will automatically adjust for the substrate diameter.
 - 7.5.4. To unload wafers push the lock bar, this will turn off the green light.
 - 7.5.5. Never open the doors if a process is being run. This will create an error.
- 7.6. Log In
- 7.6.1. Ensure no one is using the tool.
 - 7.6.2. To log in or out the user must click on the padlock icon, which is located on the system status pad.
 - 7.6.3. Select the user name from the drop down list.
 - 7.6.4. Enter the correct password.
 - 7.6.5. Choose the appropriate action.
 - 7.6.6. Click ok.
- 7.7. Operator Panel
- 7.7.1. The top portion of this panel contains a scrollable list of processes or wafer path files.
 - 7.7.2. The stop/pause/run buttons are only active when a process has been selected.

- 7.7.3. Select a file name (process) by clicking on it.
 - 7.7.4. Select the appropriate wafers to be coated or developed.
 - 7.7.5. Then choose an operation, stop/pause/run
 - 7.7.6. An icon to the left of the file name will indicate the state of the process.
 - 7.8. Resource Icons
 - 7.8.1. The right hand portion of the system status page contains an icon (status panel) for each of the system resources.
 - 7.8.2. Panels will change in real time to display general status information.
 - 7.8.3. For a more detailed status screen you can either double click on the resource icon or right click on the icon.
 - 7.9. Edge Bead Removal
 - 7.9.1. This operation places a small stream of resist solvent (NANO EBR) at the edge of the wafer (about 2mm from edge) to remove the edge bead created at the spin coat operation.
 - 7.9.2. The edge bead step should be performed after the bake step. If performed after the coat step, you may thin out the resist.
 - 7.10. Cotton Candy
 - 7.10.1. The ACS performs a self clean of the bowl after a batch to help in removing any cotton candy.
 - 7.10.2. NANO EBR is used to clean the bowl.
 - 7.11. Automatic Dispense
 - 7.11.1. Shipley 1813 is automatically dispensed, which means there is no syringe.
 - 7.11.2. Typically 4 to 5mL of Shipley 1813 is dispensed onto the substrate.
 - 7.11.3. Prior to the first substrate being coated there is a pre-dispense to remove any dried photo resist from the needle.
 - 7.11.4. Nozzle clean is programmed into all the coat steps.
 - 7.12. Errors
 - 7.12.1. If you receive any errors on the system, make a note of it and call the tool owner.
 - 8. **Waste Products**
 - 8.1. Broken wafers are to be discarded in the glass trash. Do not wrap in clean room wipes.
 - **Report all accidents (injuries, spills, fires) to the SSEL On Call or other SSEL staff. For emergencies during non-business hours, call the SSEL Emergency Response Team at (734) 764-4127 or Department of Public Safety at (734) 763-1131.**
-